

Positive Lead	Measurement / Action	Negative Lead
C2480-2	Ω	C2512A-5

Is the resistance less than 3 ohms?

Yes	INSTALL a new camera selection switch. REFER to: Parking Aid Switch . If the concern is still present after replacing the switch, GO to L6
No	REPAIR the circuit.

L6 CHECK FOR CORRECT IPMB (IMAGE PROCESSING MODULE B) OPERATION

Ignition OFF.

Disconnect and inspect the IPMB and related in-line connectors.

Repair:

corrosion (install new connector or terminals - clean module pins)

damaged or bent pins - install new terminals/pins

pushed-out pins - install new pins as necessary

Reconnect the IPMB and related in-line connectors. Make sure they seat and latch correctly.

Operate the system and determine if the concern is still present.

Is the concern still present?

Yes	CHECK OASIS for any applicable Technical Service Bulletins (TSBs). If a TSB exists for this concern, DISCONTINUE this test and FOLLOW the TSB instructions. If no Technical Service Bulletins (TSBs) address this concern, INSTALL a new IPMB.
No	The system is operating correctly at this time. The concern may have been caused by a loose or corroded connector. ADDRESS the root cause of any connector or pin issues.

DIAGNOSIS AND TESTING > PARKING AID > PINPOINT TEST(S) > PINPOINT TEST M : THE VISUAL PARK AID ALERT IS INOPERATIVE - VEHICLES WITH 360 DEGREE VIEW CAMERA

Normal Operation and Fault Conditions

REFER to: Parking Aid - System Operation and Component Description .

Possible Causes

- Communication concern