

Yes	CHECK OASIS for any applicable Technical Service Bulletins (TSBs). If a TSB exists for this concern, DISCONTINUE this test and FOLLOW the TSB instructions. If no Technical Service Bulletins (TSBs) address this concern, INSTALL a new IPMB.
No	The system is operating correctly at this time. The concern may have been caused by a loose or corroded connector. ADDRESS the root cause of any connector or pin issues.

DIAGNOSIS AND TESTING > PARKING AID > PINPOINT TEST(S) > PINPOINT TEST O : THE MANUAL ZOOM IS INOPERATIVE - VEHICLES WITH 360 DEGREE VIEW CAMERA

Normal Operation and Fault Conditions

REFER to: Parking Aid - System Operation and Component Description .

Possible Causes

- Communication concern
- Rear parking aid camera
- LIN concern
- APIM concern

Visual Inspection and Diagnostic Pre-Checks

- Perform an APIM reset and reevaluate the concern prior to following this pinpoint test. REFER to: Reset the SYNC Module [APIM] .
- If the rear parking aid camera is not configured after replacement, some video functions will be inoperative. Verify the rear parking aid camera configuration using the diagnostic scan tool.

DIAGNOSIS AND TESTING > PARKING AID > PINPOINT TEST(S) > PINPOINT TEST O : THE MANUAL ZOOM IS INOPERATIVE - VEHICLES WITH 360 DEGREE VIEW CAMERA > PINPOINT TEST O : THE MANUAL ZOOM IS INOPERATIVE - VEHICLES WITH 360 DEGREE VIEW CAMERA

O1 PERFORM A NETWORK TEST

Ignition ON.

Using a diagnostic scan tool, perform a network test.

Do all modules pass the network test?

Yes	GO to O2
------------	----------