

Operate the system and determine if the concern is still present.

**Is the concern still present?**

|            |                                                                                                                                                                                                                                                                                      |
|------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| <b>Yes</b> | CHECK OASIS for any applicable Technical Service Bulletins (TSBs). If a Technical Service Bulletin (TSB) exists for this concern, DISCONTINUE this test and FOLLOW the Technical Service Bulletin (TSB) instructions. If no Technical Service Bulletins (TSBs) address this concern, |
| <b>No</b>  | The system is operating correctly at this time. The concern may have been caused by a loose or corroded connector. ADDRESS the root cause of any connector or pin issues.                                                                                                            |

**DIAGNOSIS AND TESTING > PARKING AID > PINPOINT TEST(S) > PINPOINT TEST R : DTC (DIAGNOSTIC TROUBLE CODE) U0253:87**

Refer to Module Communications Network for schematic and connector information.

**Normal Operation and Fault Conditions**

The IPMB communicates with the APIM through the HS-CAN2, GWM and HS-CAN1.

| DTC      | Description                                                                  | Fault Trigger Conditions                                                                                                                 |
|----------|------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------------------------------|
| U0253:87 | Lost Communication With Accessory Protocol Interface Module: Missing Message | Sets in continuous memory in the IPMB if expected messages from the APIM are not received for 5 seconds or more when the ignition is on. |

**Possible Causes**

- Communication network concern
- APIM
- IPMB
- GWM

**DIAGNOSIS AND TESTING > PARKING AID > PINPOINT TEST(S) > PINPOINT TEST R : DTC (DIAGNOSTIC TROUBLE CODE) U0253:87 > PINPOINT TEST R : DTC (DIAGNOSTIC TROUBLE CODE) U0253:87**

R1 VERIFY THE CUSTOMER CONCERN

Ignition ON.

Verify whether an observable symptom present.