

Operate the system and determine if the concern is still present.

Is the concern still present?

Yes	CHECK OASIS for any applicable Technical Service Bulletins (TSBs). If a TSB exists for this concern, DISCONTINUE this test and FOLLOW the TSB instructions. If no Technical Service Bulletins (TSBs) address this concern, INSTALL a new SCCM. REFER to: Steering Column Control Module (SCCM) .
No	The system is operating correctly at this time. The concern may have been caused by a loose or corroded connector. ADDRESS the root cause of any connector or pin issues.

DIAGNOSIS AND TESTING > WIPERS AND WASHERS > PINPOINT TESTS > PINPOINT TEST C : THE HIGH SPEED WINDSHIELD WIPERS ARE INOPERATIVE

Normal Operation and Fault Conditions

REFER to: Wipers and Washers - System Operation and Component Description .

Possible Sources

- Windshield wiper motor
- Wiper/washer switch
- SCCM

DIAGNOSIS AND TESTING > WIPERS AND WASHERS > PINPOINT TESTS > PINPOINT TEST C : THE HIGH SPEED WINDSHIELD WIPERS ARE INOPERATIVE > PINPOINT TEST C : THE HIGH SPEED WINDSHIELD WIPERS ARE INOPERATIVE

C1 CHECK THE INPUT TO THE SCCM (STEERING COLUMN CONTROL MODULE) USING THE FRONT WIPER COMMAND HIGH SPEED (F_WIP_FAST_SW) PID (PARAMETER IDENTIFICATION)

Ignition ON.

Using a diagnostic scan tool, view the SCCM Parameter Identifications (PIDs).

Using a diagnostic scan tool, view the SCCM PID F_WIPE_FAST_SW.

Place the wiper/washer switch to the high speed setting.

Does the PID indicate the wiper/washer switch is in the high speed setting?

Yes	INSTALL a new windshield wiper motor. REFER to: Windshield Wiper Motor .
No	INSTALL a new wiper/washer switch. REFER to: Steering Column Multifunction Switch LH . TEST the system for normal operation. If the concern is still present, INSTALL a new SCCM. REFER to: Steering Column Control Module (SCCM) .