

Yes	CHECK OASIS for any applicable Technical Service Bulletins (TSBs). If a TSB exists for this concern, DISCONTINUE this test and FOLLOW TSB instructions. If no Technical Service Bulletins (TSBs) address this concern,
No	The system is operating correctly at this time. The concern may have been caused by module connections. ADDRESS the root cause of any connector or pin issues.

DIAGNOSIS AND TESTING > LOCKS, LATCHES AND ENTRY SYSTEMS > PINPOINT TESTS > PINPOINT TEST Z : U0140:00

Normal Operation and Fault Conditions

The DDM/ PDM communicates with the BCM over the CAN. If the DDM/ PDM does not receive messages from the BCM, features such as the puddle lamps, exterior mirror turn signal and door switch illumination can be inoperative.

DDM/ PDM DTC Fault Trigger Conditions

DTC	Description	Fault Trigger Conditions
U0140:00	Lost Communication With Body Control Module: No Sub-Type Information	Sets when the DDM/ PDM detects data messages are missing from the BCM.

Possible Causes

- Network communication concern
- DDM/ PDM
- BCM

DIAGNOSIS AND TESTING > LOCKS, LATCHES AND ENTRY SYSTEMS > PINPOINT TESTS > PINPOINT TEST Z : U0140:00 > PINPOINT TEST Z : U0140:00

Z1 VERIFY THE CUSTOMER CONCERN

Ignition ON.

Verify there is an observable symptom present.

Is an observable symptom present?

Yes	GO to Z2
No	The system is operating normally at this time. The DTC may have been set due to high network traffic or an intermittent fault condition.