

Yes	CHECK OASIS for any applicable Technical Service Bulletins (TSBs). If a TSB exists for this concern, DISCONTINUE this test and FOLLOW the TSB instructions. If no Technical Service Bulletins (TSBs) address this concern, INSTALL a new GPSM. REFER to: Global Positioning System Module (GPSM) .
No	The system is operating correctly at this time. The concern may have been caused by module connections. ADDRESS the root cause of any connector or pin issues.

DIAGNOSIS AND TESTING > INFORMATION AND ENTERTAINMENT SYSTEM > PINPOINT TESTS > PINPOINT TEST AU : U3003:17

DTC Fault Trigger Conditions

DTC	Description	Fault Trigger Conditions
U3003:17	Battery Voltage: Circuit Voltage Above Threshold	Set by the ACM, APIM, audio DSP module, DACMC, FCIM, and GPSM when the supply voltage is more than 15.8 volts for more than 250 milliseconds during normal operation or the self-test.

Possible Sources

- ACM
- APIM
- Audio DSP module
- DACMC
- FCIM
- GPSM

DIAGNOSIS AND TESTING > INFORMATION AND ENTERTAINMENT SYSTEM > PINPOINT TESTS > PINPOINT TEST AU : U3003:17 > PINPOINT TEST AU : U3003:17

AU1 RECHECK FOR DTC (DIAGNOSTIC TROUBLE CODE) U3003:17

Ignition ON.

Using a diagnostic scan tool, clear the Diagnostic Trouble Codes (DTCs) for the module in question.

Wait at least 10 seconds.