

Yes	CHECK OASIS for any applicable Technical Service Bulletins (TSBs). If a TSB exists for this concern, DISCONTINUE this test and FOLLOW the TSB instructions. If no Technical Service Bulletins (TSBs) address this concern, INSTALL a new GPSM. REFER to: Global Positioning System Module (GPSM) .
No	The system is operating correctly at this time. The concern may have been caused by module connections. ADDRESS the root cause of any connector or pin issues.

GENERAL PROCEDURES > BEZEL DIAGNOSTICS

Check

1.

 **WARNING:** Before beginning any service procedure in this article, refer to Health and Safety Precautions in GENERAL INFORMATION . Failure to follow this instruction may result in serious personal injury.

Refer to: Health and Safety Precautions .

 **NOTE:** If there is a concern with one of the following components and Bezel Diagnostics cannot be accessed, obtain the module part number by referencing the label attached to the module.

- Inoperative (blank or does not power on) FDIM
- Inoperative FCIM
- Inoperative steering wheel switch (for vehicles without a CD player)

Refer to appropriate article to diagnose the inoperative component.

2.

Ignition ON.

3.

Operate the audio system in AM/ FM mode.

* For vehicles **with** a CD player, press and hold the EJECT button, and within 1 second, press and hold the SEEK UP button. If supported, the Speaker Walk-Around Test will begin, and the display will indicate each speaker as it is tested.

* For vehicles **without** a CD player, simultaneously press and hold the steering wheel SEEK UP switch and FCIM TUNE UP button. If supported, the Speaker Walk-Around Test will begin, and the display will indicate each speaker as it is tested.