

		new ACM. REFER to: Audio Front Control Module (ACM) .
U2101:00	Control Module Configuration Incompatible: No Sub Type Information	This DTC sets due to an incomplete or incorrect DACMC PMI. CHECK the vehicle service history for recent service actions related to the DACMC or ACM. If there have been recent service actions with the DACMC or ACM, REPEAT/PERFORM the DACMC PMI procedure as directed by the diagnostic scan tool. REFER to: Module Configuration - System Operation and Component Description . See PMI. If there have been no recent service actions, the DACMC has failed to retain configuration data. INSTALL a new ACM. REFER to: Audio Front Control Module (ACM) .
U3000:41	Control Module: General Checksum Failure	CLEAR the Diagnostic Trouble Codes (DTCs). WAIT at least 10 seconds. REPEAT the self-test. If DTC U3000:41 is retrieved again, INSTALL a new ACM. REFER to: Audio Front Control Module (ACM) .
U3000:42	Control Module: General Memory Failure	CLEAR the Diagnostic Trouble Codes (DTCs). WAIT at least 10 seconds. REPEAT the self-test. If DTC U3000:42 is retrieved again, INSTALL a new ACM. REFER to: Audio Front Control Module (ACM) .
U3000:92	Control Module: Performance or Incorrect Operation	GO to Pinpoint Test F
U3000:94	Control Module: Unexpected Operation	If an observable symptom is not present, DISREGARD this DTC. If an observable symptom is present, GO to Pinpoint Test F
U3003:16	Battery Voltage: Circuit Voltage Below Threshold	GO to Pinpoint Test AT
U3003:17	Battery Voltage: Circuit Voltage Above Threshold	GO to Pinpoint Test AU