

Yes	INSTALL a new media hub. REFER to: Media Hub . RETEST the system for normal operation. If the concern is still present, GO to X5
No	REPAIR the circuit in question.

X5 CHECK FOR CORRECT APIM (SYNC MODULE) OPERATION

Ignition OFF.

Disconnect and inspect the APIM connector.

Repair:

Corrosion (clean module pins or install new connectors or terminals)

Damaged or bent pins (install new terminals or pins)

Pushed-out pins (install new pins as necessary)

Reconnect the APIM connector. Make sure it seats and latches correctly.

Operate the system and determine if the concern is still present.

Is the concern still present?

Yes	CHECK OASIS for any applicable Technical Service Bulletins (TSBs). If a TSB exists for this concern, DISCONTINUE this test and FOLLOW the TSB instructions. If no Technical Service Bulletins (TSBs) address this concern, PERFORM the APIM Hardware Test. Refer to APIM HARDWARE TESTING .
No	The system is operating correctly at this time. The concern may have been caused by module connections. ADDRESS the root cause of any connector or pin issues.

DIAGNOSIS AND TESTING > INFORMATION AND ENTERTAINMENT SYSTEM > PINPOINT TESTS > PINPOINT TEST Y : UNABLE TO PAIR BLUETOOTH DEVICE

Normal Operation and Fault Conditions

REFER to: Information and Entertainment System - System Operation and Component Description . See Bluetooth Mode and SYNC ® System.

Possible Sources

- Incompatible Bluetooth device
- APIM

DIAGNOSIS AND TESTING > INFORMATION AND ENTERTAINMENT SYSTEM >