

Positive Lead	Measurement / Action	Negative Lead
C205-3	Ω	C205-6

Is the resistance greater than 10, 000 ohms?

Yes	GO to A6
No	REPAIR the circuit in question.

A6 CHECK THE INSTRUMENT PANEL DIMMER SWITCH

Perform the instrument panel dimmer switch component test (part of the headlamp switch component test). Refer to Component Testing for schematic and connector information.

Does the instrument panel dimmer switch pass the component test?

Yes	GO to A7
No	INSTALL a new headlamp switch. REFER to: Headlamp Switch .

A7 CHECK FOR CORRECT BCM (BODY CONTROL MODULE) OPERATION

Disconnect and inspect all BCM connectors.

Repair:

corrosion (install new connector or terminals - clean module pins)

damaged or bent pins - install new terminals/pins

pushed-out pins - install new pins as necessary

Reconnect the BCM connectors. Make sure they seat and latch correctly.

Operate the system and determine if the concern is still present.

Is the concern still present?

Yes	CHECK OASIS for any applicable Technical Service Bulletins (TSBs). If a TSB exists for the concern, DISCONTINUE this test and FOLLOW the TSB instructions. If no TSB address this concern, .
No	The system is operating correctly at this time. The concern may have been caused by module connections. ADDRESS the root cause of any connector or pin issues.