

PUBLISHED: 24-MAY-2019
2020.0 DEFENDER (LE), 413-09

WARNING DEVICES

SERVICE INDICATOR RESET (G2319823)

mcx30.com

mcx30.com

SYNCHRONIZATION

NOTES:

- For Diesel vehicles and depending on the specification, this procedure will only reset the oil dilution counter after a service.
- To reset the time and distance counters for these vehicles, **complete the configuration step.**

1.

NOTE:

Make sure the Jaguar Land Rover approved diagnostic equipment is not connected to the vehicle.

Set the ignition to the ON position.

2.

Open the hood.

3.

Open the drivers door.

4.

NOTE:

If the accelerator pedal pressed before the brake pedal this will cause Brake Over Accelerator (BOA) logic and will default the accelerator pedal to 0%. If this happens the service reset procedure will have to be restarted.

Fully depress the brake pedal then the accelerator pedal and hold for 10 seconds.

5.

A 'Service Reset' message will appear on the instrument cluster.

6.

Release the accelerator and brake pedals and set the ignition to the OFF position.

7.

Set the ignition to the ON position and check the message has been cleared.

8.

If the message remains, repeat the process.

CONFIGURATION

1. Using the Jaguar Land Rover approved diagnostic equipment, reset the Service Interval Indicator (SII).

cmjjaGFyZG1vcnRvbjsyMDIwLTASLTE4VDA2OjM5OjM1LjM0No7OTAuMTk5LjEyMS4xMTc7

mcx30.com