

2022 CHEVROLET CORVETTE SERVICE MANUAL

- SEARCH

1. Body Systems
2. Fixed and Moveable Windows
3. Repair Instructions
- 4.

Rear Window Normalization

The rear sliding window motor that has not been normalized may no longer stop at the full UP position which may occur when the rear sliding window motor has been disconnected or replaced

Rear Sliding Window Motor Normalization Procedure

1. Note:

The convertible top must be closed and firmly latched

2. Ignition ON.
3. Pull the appropriate driver front side door control switch up until the rear sliding window stops (window may not stop at the full UP position)
4. Release driver front side door control switch for 2 seconds
5. Pull the appropriate driver front side door control switch up for 30 seconds

The rear sliding window should now be normalized and the rear sliding window should perform the full UP position when commanded