

Proceed in the reverse order to removal.



Repair-70x02x04x02-01x37-1-31-1.xml



XSL version : 3.02 du 22/07/11

mcx30.com

HEATERBULKHEAD:REPLACEMENT



Note, one or more warnings are present in this procedure



1. COMPOSITION OF THE SPARE PART

No.	Description	Thickness (mm)
	Heater bulkhead rear section	0.7
	Windscreen aperture lower cross member bracket	1.2
	Heater bulkhead front section	1.5
	Left heater bulkhead reinforcement	1.5
	Air filter mounting support	1
	Left wiper mounting bridging piece	1.6
	Right wiper mounting bridging piece	1.5
	Right Heater bulkhead reinforcement	1.5

2. IN THE EVENT OF REPLACEMENT

- ☐ The options for replacing this part are as follows:
- ☒ complete replacement