

MULTIMEDIA WIRING : REMOVAL - REFITTING



Note, one or more warnings are present in this procedure



WARNING

■ To avoid all risk of damage to the systems, apply the safety and cleanliness instructions and operation recommendations before carrying out any repair:

■ [Vehicle: Precautions for the repair](#) .

REMOVAL

1. REMOVAL PREPARATION OPERATION



WARNING

DANGER : Risk of serious injuries due to the short-circuiting or the untimely triggering of an electrical system (pyrotechnical parts, windscreen wiper motor, electric fan, etc.) following possible loopback of the 12-volt supply circuit by the voltage transformer.

Please adhere to the instructions regarding cut-off of the 12-volt supply circuit.


If the procedure fails, do not continue with your task and ask an employee who is qualified and authorized to work on a high-voltage onboard network to perform a diagnostic [Vehicle: Precautions for the repair](#) .

■ Lockout the 12V supply circuit [12 V supply circuit : Lockout - Removal of lockout](#) .


■ Remove the glovebox [Dashboard assembly: Exploded view](#)

2. REMOVAL OPERATION

■ Disconnect the carsharing module connector [Carsharing module : Removal - Refitting](#) .




- Remove the centre front panel following the direction in the arrow.




■ Disconnect (1) :

- the control panel connector,
- the radio navigation system connector.

LEFT-HAND DRIVE



RIGHT-HAND DRIVE



Pull the clip wiring(2) , (3) .

Remove the carsharing module wiring(4) .

REFITTING

1. REFITTING OPERATION

Proceed in the reverse order to removal.

2. FINAL OPERATION

Remove the lockout of the 12V supply circuit [12 V supply circuit : Lockout - Removal of lockout](#) .



Repair-32x05x32-01x37-1-3-1.xml



XSL version : 3.02 du 22/07/11

mcx30.com