

Audio Unit -**Torque Specifications**

Description	Nm	lb-ft
Audio amplifier bolts	10	7

mcx30.com

Audio Unit - Audio System

Diagnosis and Testing

For additional information.

REFER to: [Information and Entertainment System](#) (415-00 Information and Entertainment System - General Information, Diagnosis and Testing).

mcx30.com

Audio Unit - Audio Unit

Removal and Installation

Removal

- NOTE: Removal steps in this procedure may contain installation details.

1.



2. Torque: 2.5 Nm




3.



4. 4. NOTE: LHD illustration shown, RHD is similar.




5.



6.



7.




E123213

8.



E 123214

9. Torque: 2.5 Nm




E123298


10.



E123218




11.



12. Torque: 2.5 Nm





E123221

13. Torque: 2.5 Nm

14. **14.** NOTE: Do not disassemble further if the component is removed for access only.

Torque: 2.5 Nm



E122787

Installation

1. To install, reverse the removal procedure.

Audio Unit - Audio Amplifier

Removal and Installation


Removal

1. Disconnect the battery ground cable.
For additional information, refer to: [Specifications](#) (414-00 Battery and Charging System - General Information, Specifications).
2. Remove the RH front seat.
For additional information, refer to: [Front Seat](#) (501-10 Seating, Removal and Installation).

3.  **CAUTION:** Cover fiber optic cable connectors to minimize dust ingress and avoid bending the cables in a radius of less than 30 mm.

Remove the amplifier.

- Remove the 4 bolts.
- Disconnect the 5 electrical connectors.



E54204

Installation

1. Install the amplifier.
 - Install the bolts and tighten to 10 Nm (7 lb.ft).
 - Connect and secure the electrical connectors.
2. Install the front seat.
For additional information, refer to: [Front Seat](#) (501-10 Seating, Removal and Installation).
3. Connect the battery ground cable.
For additional information, refer to: [Specifications](#) (414-00 Battery and Charging System - General Information, Specifications).
4. Using the Land Rover approved diagnostic equipment, follow the on-screen instructions and configure the audio unit amplifier.