

PUBLISHED: 21-NOV-2016
2020.0 DEFENDER (LE), 205-04

FRONT DRIVE HALFSHAFTS

HALFSHAFT SUPPORT BRACKET (G2006913)

mcx30.com

mcx30.com

REMOVAL

1.



WARNING:

Make sure to support the vehicle with axle stands.


Raise and support the vehicle.

2.


Remove the front right halfshaft.

Refer to: [Front Right Halfshaft](#) (205-04 Front Drive Halfshafts, Removal and Installation).

3.




4.




INSTALLATION

1.



Torque: 50Nm

2.



Torque: 63Nm

3. Install the front right halfshaft.

Refer to: [Front Right Halfshaft](#) (205-04 Front Drive Halfshafts, Removal and Installation).

