

PUBLISHED: 19-FEB-2020
2020.0 DEFENDER (LE), 415-01

INFORMATION AND ENTERTAINMENT SYSTEM

FM2 AND DAB ANTENNA AMPLIFIER (G2413597)

mcx30.com

REMOVAL


 NOTE:

- This procedure contains some variation in the illustrations depending on the vehicle specification, but the essential information is always correct.
- This procedure contains illustrations showing certain components removed to provide extra clarity.

1. Remove the headliner.


Refer to: [Headliner - 110](#) (501-05 Interior Trim and Ornamentation, Removal and Installation).

- 2.



Disconnect the 2 electrical connectors.

3.



- Remove the bolt.
- Release the clip.
- Remove the FM2 and DAB antenna.

INSTALLATION

1.



NOTE:

Make sure that the component is correctly located.

- Install the FM2 and DAB antenna.
- Install and tighten the bolt.

Torque: 5Nm

2.

Connect the 2 electrical connectors to the FM2 and DAB antenna.

3.

Install the headliner.

Refer to: [Headliner - 110](#) (501-05 Interior Trim and Ornamentation, Removal and Installation).