

PUBLISHED: 28-OCT-2019
2020.0 DEFENDER (LE), 501-05

INTERIOR TRIM AND ORNAMENTATION

A-PILLAR LOWER TRIM PANEL (G2414049)

mcx30.com

REMOVAL


⚠ CAUTION:

Make sure that excessive force is not used. Failure to follow this instruction may result in damage to the vehicle.

△ NOTE:


- This procedure contains some variation in the illustrations depending on the vehicle specification, but the essential information is always correct.
- This procedure contains illustrations showing certain components removed to provide extra clarity.
- This procedure Contains illustrations for the right side components, left side components are similar.

1.




- Remove the 4 bolts.
- Remove the instrument panel outer side trim.

2.



- Release the 2 clips.
- Remove the A-pillar center trim panel.


3.



- Release the 3 clips.
- Release the treadplate.

ⓘ CAUTION:

Do not close the door when the lower trim is not in the correct installed position



- Release the 2 clips.
- Move the hood release lever.
- Remove the A-pillar lower trim panel.

INSTALLATION

1.



NOTE:

Make sure that the clips are correctly installed to the trim.

- Install the A-pillar lower trim panel.
- Install the 2 clips.

2.



NOTE:

Make sure that the clips are correctly installed to the trim.

- Install the treadplate.
- Install the 3 clips.

3.



NOTE:

Make sure that the clips are correctly installed to the trim.

- Install the A-pillar center trim panel.
- Install the 2 clips.


4.

- Install the instrument panel outer side trim.
- Install and tighten the 4 bolts.
Torque: 2.5Nm

5.

⚠ CAUTION:

Make sure that the weatherstrip is not stretched on installation.



Use a suitable tool to reposition the door aperture seal.

6.

Make sure the hood is closed after the work is completed.