

PUBLISHED: 16-APR-2019
2020.0 DEFENDER (LE), 501-05

INTERIOR TRIM AND ORNAMENTATION

ENGINE COVER – INGENIUM I4 2.0L PETROL (G2344513)


mcx30.com

REMOVAL

 NOTES:

- This procedure contains some variation in the illustrations depending on the vehicle specification, but the essential information is always correct.
- This procedure contains illustrations showing certain components removed to provide extra clarity.

1.



- Remove the oil filler cap.
- Release the 4 clips.
- Remove the engine cover.

1.

 CAUTION:

Do not use excessive force to install the component.

- Install the engine cover.
- Install the oil filler cap.

cmjjaGFyZG1vcnRvbjcyMDIwLTASLTE4VDEyOjAxOjI1Ljc2Nm7OTUuNDAuMTg5LjUwOw==

mcx30.com