

PUBLISHED: 21-JAN-2020
2020.0 DEFENDER (LE), 501-10

SEATING

SECOND ROW SEAT CUSHION BLOWER (G2414290)

mcx30.com

REMOVAL

 NOTE:

- This procedure contains illustrations showing certain components removed to provide extra clarity.
- This procedure contains some variation in the illustrations depending on the vehicle specification, but the essential information is always correct.
- This procedure contains illustrations for right side components, left side components are similar.


1. Disconnect the startup battery ground cable.

Refer to: [Startup Battery Disconnect and Connect](#) (414-00 Battery and Charging System - General Information, General Procedures).

2. Remove the second row seats.


Refer to: [Second Row Right Seat - 110](#) (501-10 Seating, Removal and Installation).

- 3.



Release the 5 clips.

4.



- Disconnect the 2 electrical connectors.
- Remove the second row seat cushion blower.

INSTALLATION

1.

- Install the second row seat cushion blower.
- Connect the 2 electrical connectors to the blower.

2.

Install the 5 second row seat cushion clips.

3.

Install the second row seat.

Refer to: [Second Row Right Seat - 110](#) (501-10 Seating, Removal and Installation).

4.

Connect the startup battery ground cable.

Refer to: [Startup Battery Disconnect and Connect](#) (414-00 Battery and Charging System - General Information, General Procedures).