

PUBLISHED: 16-JAN-2020
2020.0 DEFENDER (LE), 501-10

SEATING

SECOND ROW RIGHT SEAT CUSHION HEATER ELEMENT [G2414492]

mcx30.com


REMOVAL

 NOTE:

- This procedure contains illustrations showing certain components removed to provide extra clarity.
- This procedure contains some variation in the illustrations depending on the vehicle specification, but the essential information is always correct.
- This procedure contains illustrations for right side components, left side components are similar.

1. Remove the second row right seat cushion cover.
Refer to: [Second Row Right Seat Cushion Cover](#) (501-10 Seating, Removal and Installation).

- 2.



Remove the second row seat cushion heater element.

INSTALLATION

1. Install the second row seat cushion heater element.

2. Install the second row seat cushion cover.

Refer to: [Second Row Right Seat Cushion Cover](#) (501-10 Seating, Removal and Installation).

cmjjaGFyZG1vbnRvb3RyMDIwLTA5LTE4VDEyOjMxOjQwLjQ4Mlo7OTluNDAuMTg5SjUwOw==

mcx30.com