

PUBLISHED: 28-AUG-2019
2020.0 DEFENDER (LE), 501-12

INSTRUMENT PANEL AND CONSOLE

FLOOR CONSOLE – VEHICLES WITHOUT: STOWAGE COMPARTMENT (G2416807)

mcx30.com

REMOVAL

 NOTE:

- This procedure contains some variation in the illustrations depending on the vehicle specification, but the essential information is always correct.
- This procedure contains illustrations showing certain components removed to provide extra clarity.

1.




- Remove the 4 bolts.
- Remove the floor console center trim panel.

2.


 NOTE:

Only complete the following step(s) if a new component is to be installed.



Remove the floor console insulator foam.

3.



- Remove the 5 bolts.
- Remove the cup holder from the floor console center trim panel.

INSTALLATION

1.



NOTE:

Steps 1-2 are only required if the components were previously removed.

- Install the cup holder.
- Install and tighten the 5 bolts.

Torque: 1.5Nm

2.

Install the floor console insulator foam.

3.

- Install the floor console center trim panel.
- Install and tighten the 4 bolts.

Torque: 1.7Nm