


2022 CHEVROLET CORVETTE SERVICE MANUAL

- SEARCH

- 1. Body Hardware and Trim
- 2. Exterior Trim
- 3. Repair Instructions
- 4.

Body Side Upper Front Applique Replacement



[Click here for full size](#)
[Windshield Frame Weatherstrip Replacement](#)

•

Roof Lift Off Panel Replacement

Fastener Caution.

Tighten

2.5N-m (22 lb in)

Callout	Component Name
Preliminary Procedures	
1. Reposition the weatherstrip as necessary.	
1	Body Side Upper Front Applique Bolt - Upper
	Caution:
	Refer to