


2022 CHEVROLET CORVETTE SERVICE MANUAL

- SEARCH

- 1. Body Hardware and Trim
- 2. Exterior Trim
- 3. Repair Instructions
- 4.

Body Side Upper Rear Applique Replacement (Coupe)



[Click here for full size](#)
Roof Panel Rear Extension Replacement

Callout	Component Name
Preliminary Procedure	
1	Body Side Upper Rear Applique Procedure 1. Release the retainers. 2. Clean the mounting area using a lint-free cloth dampened with a 50/50 mixture of isopropyl alcohol and water.