

2022 CHEVROLET CORVETTE SERVICE MANUAL

- SEARCH

- 1. Body Hardware and Trim
- 2. Exterior Trim
- 3. Repair Instructions
- 4.

Folding Top Stowage Compartment Trim Panel Vent Replacement

Click here for full size
Folding Top and Folding Top Stowage Compartment Lid Operation Warning.

Warning:

Refer to

Folding Top Stowage Compartment Lid Heat Warning.

Caution:

Refer to

Folding Top Guidelines Caution.

Preliminary Procedure

Operate the folding top to the fully open position.

Folding Top and Folding Top Stowage Compartment Lid Operation

Fastener Caution.

Tighten

4.7N-m (42 lb in)

Callout	Component Name
Warning:	
Refer to	
1	Folding Top Stowage Compartment Trim Panel Vent Nut [4x] Caution: Refer to
2	Folding Top Stowage Compartment Trim Panel Vent