


2022 CHEVROLET CORVETTE SERVICE MANUAL

- SEARCH

- 1. Body Hardware and Trim
- 2. Exterior Trim
- 3. Repair Instructions
- 4.

Front Outer Grille Opening Bezel Replacement



[Click here for full size](#)
Front Bumper Fascia Removal and Installation

- Place the front bumper fascia down on a clean protected surface.

Fastener Caution.

Tighten

2.5N-m (22 lb in)

Callout	Component Name
Preliminary Procedures	
1.	
1	Front Outer Grille Opening Bezel Bolt [3x] Caution: Refer to
2	Front Outer Grille Opening Bezel Procedure Release the retainer tabs.