


2022 CHEVROLET CORVETTE SERVICE MANUAL

- SEARCH

- 1. Body Hardware and Trim
- 2. Exterior Trim
- 3. Repair Instructions
- 4.

Liftgate Panel Ventilating Molding Replacement



Click here for full size
Fastener Caution.

Tighten

4.7 N-m (42 lb in)

Callout	Component Name
1	Liftgate Panel Ventilating Molding Bolt [9x]
	Caution:
	Refer to
2	Liftgate Panel Ventilating Molding