


2022 CHEVROLET CORVETTE SERVICE MANUAL

- SEARCH

- 1. Body Hardware and Trim
- 2. Exterior Trim
- 3. Repair Instructions
- 4.

Rear Bumper Fascia Center Grille Replacement



[Click here for full size](#)
Rear Bumper Fascia Removal and Installation

Fastener Caution.

Tighten

2.5 N-m (22 lb in)

Callout	Component Name
Preliminary Procedure	
1	Rear Bumper Fascia Center Grille Bolt [13x] Caution: Refer to
2	Rear Bumper Fascia Center Grille