


2022 CHEVROLET CORVETTE SERVICE MANUAL

- SEARCH

- 1. Body Hardware and Trim
- 2. Floor Coverings and Headlinings
- 3. Repair Instructions
- 4.

Driver Footrest Bracket Replacement



[Click here for full size
Driver Footrest Replacement](#)

•

Front Side Door Sill Garnish Molding Replacement

- Reposition the front floor carpet as needed.

Fastener Caution.

Tighten

3 N-m (27 lb in)

Callout	Component Name
Preliminary Procedures	
1.	
1	Driver Footrest Bracket Nut [3x]
	Caution:
	Refer to
2	Driver Footrest Bracket