


2022 CHEVROLET CORVETTE SERVICE MANUAL

- **SEARCH**


1. **Body Hardware and Trim**
2. **Instrument Panel and Console Trim**
3. **Repair Instructions**
- 4.

Front Floor Console Applique Replacement - Left Side

Removal Procedure




1. [Click here for full size](#)
2. Remove the left body hinge pillar garnish molding (1). [Body Hinge Pillar Garnish Molding Replacement](#)
3. Remove the left windshield garnish molding. [Windshield Garnish Molding Replacement](#)




4. [Click here for full size](#)

5. Remove the left instrument panel trim pad radio speaker opening cover (1).Instrument Panel Trim Pad Radio Speaker Opening Cover Replacement




6.
[Click here for full size](#)

7. Remove the left radio front speaker grille molding (2).Radio Front Speaker Grille Molding Replacement




8.
[Click here for full size](#)

9. Remove the left instrument panel outer trim cover (1).Instrument Panel Outer Trim Cover Replacement




10.
[Click here for full size](#)

11. Instrument Panel Knee Bolster (2) >> Remove - Instrument Panel Knee Bolster Replacement




12.
[Click here for full size](#)

13. Front Floor Rear Console Side Trim Panel - Left Side (1) >> Remove - Front Floor Rear Console Side Trim Panel Replacement - Left Side




14. [Click here for full size](#)
15. Front Floor Console Applique Bolt (1) >>> Remove
16. Front Floor Console Applique - Left Side (2) >>> Remove

Installation Procedure




1. [Click here for full size](#)
2. Front Floor Console Applique - Left Side (2) >>> Install
3. Caution:
Refer to Fastener Caution.
4. Front Floor Console Applique Bolt (1) >>> Install and tighten 7>N-m (62 lb in)




5.
[Click here for full size](#)

6. Front Floor Rear Console Side Trim Panel - Left Side (1) >> Install - Front Floor Rear Console Side Trim Panel Replacement - Left Side




7.
[Click here for full size](#)

8. Instrument Panel Knee Bolster (2) >> Install - Instrument Panel Knee Bolster Replacement




9.
[Click here for full size](#)

10. Install the left instrument panel outer trim cover (1).Instrument Panel Outer Trim Cover Replacement




11.
[Click here for full size](#)

12. Install the left radio front speaker grille molding (2).Radio Front Speaker Grille Molding Replacement



13. [Click here for full size](#)
14. Install the left instrument panel trim pad radio speaker opening cover (1).Instrument Panel Trim Pad Radio Speaker Opening Cover Replacement
15. Install the left windshield garnish molding.Windshield Garnish Molding Replacement



16. [Click here for full size](#)
17. Install the left body hinge pillar garnish molding (1).Body Hinge Pillar Garnish Molding Replacement