


2022 CHEVROLET CORVETTE SERVICE MANUAL

- SEARCH

- 1. Body Hardware and Trim
- 2. Instrument Panel and Console Trim
- 3. Repair Instructions
- 4.

Front Floor Console Extension Panel Replacement



[Click here for full size](#)
Front Floor Rear Console Side Trim Panel Replacement - Right Side

Fastener Caution.

Tighten

7>N-m (62 lb in)

Callout	Component Name
Preliminary Procedures	
1. Open the instrument panel compartment door.	
2.	
1	Front Floor Console Extension Panel Bolt Caution: Refer to
2	Front Floor Console Extension Panel