


2022 CHEVROLET CORVETTE SERVICE MANUAL

- SEARCH

- 1. Body Hardware and Trim
- 2. Instrument Panel and Console Trim
- 3. Repair Instructions
- 4.

Front Floor Rear Console Side Trim Panel Replacement - Left Side



Click here for full size

Callout	Component Name
1	Front Floor Rear Console Side Trim Panel - Left Side Note: Use care not to bend or deform the panel when removing. Procedure 1. Open the armrest cover. 2. Starting at the front and working your way back, disengage the retainers using a flat-bladed plastic tool.