


2022 CHEVROLET CORVETTE SERVICE MANUAL

- SEARCH

- 1. Body Hardware and Trim
- 2. Instrument Panel and Console Trim
- 3. Repair Instructions
- 4.

Front Floor Rear Console Side Trim Panel Replacement - Right Side



Click here for full size

Callout	Component Name
1	Front Floor Rear Console Side Trim Panel - Right Side Note: Use care not to bend or deform the panel when removing. Procedure Starting at the front and working your way back, disengage the retainers using a flat-bladed plastic tool.