


2022 CHEVROLET CORVETTE SERVICE MANUAL

- **SEARCH**


1. **Body Hardware and Trim**
2. **Instrument Panel and Console Trim**
3. **Repair Instructions**
- 4.

Instrument Panel Accessory Bezel Replacement

Removal Procedure




1. [Click here for full size](#)
2. Remove the left body hinge pillar garnish molding (1). [Body Hinge Pillar Garnish Molding Replacement](#)
3. Remove the left windshield garnish molding. [Windshield Garnish Molding Replacement](#)




4. [Click here for full size](#)

5. Remove the left instrument panel trim pad radio speaker opening cover (1).Instrument Panel Trim Pad Radio Speaker Opening Cover Replacement




6.
[Click here for full size](#)

7. Remove the left radio front speaker grille molding (2).Radio Front Speaker Grille Molding Replacement




8.
[Click here for full size](#)

9. Remove the left instrument panel outer trim cover (1).Instrument Panel Outer Trim Cover Replacement




10. [Click here for full size](#)
11. Instrument Panel Accessory Bezel Bolt (1) >> Remove
12. Instrument Panel Accessory Bezel (2) >> Remove

Installation Procedure




1. [Click here for full size](#)
2. Instrument Panel Accessory Bezel (2) >> Install
3. Caution:
Refer to Fastener Caution.
4. Instrument Panel Accessory Bezel Bolt (1) >> Install and tighten 2.5N-m (22 lb in)




5. [Click here for full size](#)

6. Install the left instrument panel outer trim cover (1).Instrument Panel Outer Trim Cover Replacement



7. [Click here for full size](#)


8. Install the left radio front speaker grille molding (2).Radio Front Speaker Grille Molding Replacement



9.
[Click here for full size](#)

10. Install the left instrument panel trim pad radio speaker opening cover (1).Instrument Panel Trim Pad Radio Speaker Opening Cover Replacement

11. Install the left windshield garnish molding.Windshield Garnish Molding Replacement



12.
[Click here for full size](#)

13. Install the left body hinge pillar garnish molding (1).Body Hinge Pillar Garnish Molding Replacement