


# 2022 CHEVROLET CORVETTE SERVICE MANUAL

- SEARCH

- 1. Body Hardware and Trim
- 2. Instrument Panel and Console Trim
- 3. Repair Instructions
- 4.

## Instrument Panel Knee Bolster Replacement



[Click here for full size](#)  
Instrument Panel Outer Trim Cover Replacement

Fastener Caution.

Tighten

2.5N-m (22 lb in)

| Callout               | Component Name                                                                                                                                                                                                           |
|-----------------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| Preliminary Procedure |                                                                                                                                                                                                                          |
| 1                     | Instrument Panel Knee Bolster Bolt [2x]<br><br>Caution:<br><br>Refer to                                                                                                                                                  |
| 2                     | Instrument Panel Knee Bolster<br><br>Procedure<br><br>1. Using a flat-bladed plastic trim tool, release the retaining clips.<br><br>2. Disconnect the electrical connectors.<br><br>3. Transfer components as necessary. |