

2022 CHEVROLET CORVETTE SERVICE MANUAL

- **SEARCH**

1. **Body Hardware and Trim**
2. **Instrument Panel and Console Trim**
3. **Repair Instructions**
- 4.

Instrument Panel Lower Trim Panel Insulator Replacement - Left Side

Click here for full size

Fastener Caution.

Tighten

2.5N-m (22 lb in)

Callout	Component Name
1	Instrument Panel Lower Insulator Retainer
	Procedure
	Using a flat-bladed plastic trim tool, release the retainer
2	Instrument Panel Lower Trim Panel Insulator Bolt [3x]
	Caution:
	Refer to
3	Instrument Panel Lower Trim Panel Insulator