


2022 CHEVROLET CORVETTE SERVICE MANUAL

- SEARCH


1. Body Hardware and Trim
2. Instrument Panel and Console Trim
3. Repair Instructions
- 4.

Instrument Panel Outer Trim Cover Replacement

Removal Procedure




1. [Click here for full size](#)
2. Remove the left body hinge pillar garnish molding (1). [Body Hinge Pillar Garnish Molding Replacement](#)
3. Remove the left windshield garnish molding. [Windshield Garnish Molding Replacement](#)




4. [Click here for full size](#)

5. Remove the left instrument panel trim pad radio speaker opening cover (1).Instrument Panel Trim Pad Radio Speaker Opening Cover Replacement



6. [Click here for full size](#)

7. Remove the left radio front speaker grille molding (2).Radio Front Speaker Grille Molding Replacement




8. [Click here for full size](#)

9. Note:


Use a flat bladed plastic trim tool.

10. Remove the left instrument panel outer trim cover (1).


Installation Procedure




1.
Click here for full size
2. Install the left instrument panel outer trim cover (1).



3.
Click here for full size
4. Install the left radio front speaker grille molding (2).Radio Front Speaker Grille Molding Replacement



5. [Click here for full size](#)
6. Install the left instrument panel trim pad radio speaker opening cover (1).Instrument Panel Trim Pad Radio Speaker Opening Cover Replacement
7. Install the left windshield garnish molding.Windshield Garnish Molding Replacement



8. [Click here for full size](#)
9. Install the left body hinge pillar garnish molding (1).Body Hinge Pillar Garnish Molding Replacement