


2022 CHEVROLET CORVETTE SERVICE MANUAL

- SEARCH


1. Body Hardware and Trim
2. Instrument Panel and Console Trim
3. Repair Instructions
- 4.

Instrument Panel Switch Trim Plate Replacement

Removal Procedure




1. [Click here for full size](#)
2. Remove the left body hinge pillar garnish molding (1).Body Hinge Pillar Garnish Molding Replacement




3.
[Click here for full size](#)

4. Remove the left windshield garnish molding (2). Windshield Garnish Molding Replacement




5.
[Click here for full size](#)

6. Remove the left instrument panel trim pad radio speaker opening cover (1). Instrument Panel Trim Pad Radio Speaker Opening Cover Replacement




7.
[Click here for full size](#)

8. Remove the left radio front speaker grille molding (2).Radio Front Speaker Grille Molding Replacement




9.
[Click here for full size](#)

10. Remove the left instrument panel outer trim cover (1).Instrument Panel Outer Trim Cover Replacement



11.
[Click here for full size](#)

12. Instrument Panel Knee Bolster (2) >> Remove - Instrument Panel Knee Bolster Replacement




13.
[Click here for full size](#)

14. Instrument Panel Knee Bolster Bolt (1) >> Remove [2x]


15. Instrument Panel Switch Trim Plate (2) >> Remove

16. Transfer components as necessary.


Installation Procedure



1. [Click here for full size](#)
2. Instrument Panel Switch Trim Plate (2) >> Install
3. Caution:
Refer to Fastener Caution.
4. Instrument Panel Knee Bolster Bolt (1) >> Install and tighten [2x]2.5N-m (22 lb in)




5. [Click here for full size](#)
6. Instrument Panel Knee Bolster (2) >> Install - Instrument Panel Knee Bolster Replacement




7.
[Click here for full size](#)

8. Install the left instrument panel outer trim cover (1).Instrument Panel Outer Trim Cover Replacement




9.
[Click here for full size](#)


10. Install the left radio front speaker grille molding (2).Radio Front Speaker Grille Molding Replacement



11. [Click here for full size](#)
12. Install the left instrument panel trim pad radio speaker opening cover (1).Instrument Panel Trim Pad Radio Speaker Opening Cover Replacement



13. [Click here for full size](#)
14. Install the left windshield garnish molding (2).Windshield Garnish Molding Replacement



15.
[Click here for full size](#)

16. Install the left body hinge pillar garnish molding (1).Body Hinge Pillar Garnish Molding Replacement

mcx30.com