


2022 CHEVROLET CORVETTE SERVICE MANUAL

- SEARCH

- 1. Body Hardware and Trim
- 2. Instrument Panel and Console Trim
- 3. Repair Instructions
- 4.

Instrument Panel Trim Pad Radio Speaker Opening Cover Replacement



Click here for full size
Windshield Garnish Molding Replacement

Callout	Component Name
Preliminary Procedure	
1	Instrument Panel Trim Pad Radio Speaker Opening Cover
	Procedure
	Using a flat-bladed plastic trim tool, release the retaining clips.