


2022 CHEVROLET CORVETTE SERVICE MANUAL

- SEARCH


1. [Body Hardware and Trim](#)
2. [Instrument Panel and Console Trim](#)
3. [Repair Instructions](#)
- 4.

Instrument Panel Upper Trim Panel Cover Replacement

Removal Procedure




1. [Click here for full size](#)
2. Remove the left body hinge pillar garnish molding (1). [Body Hinge Pillar Garnish Molding Replacement](#)




3.
[Click here for full size](#)

4. Remove the left windshield garnish molding (2). Windshield Garnish Molding Replacement




5.
[Click here for full size](#)

6. Remove the left instrument panel trim pad radio speaker opening cover (1). Instrument Panel Trim Pad Radio Speaker Opening Cover Replacement



7.
[Click here for full size](#)


8. Radio Front Speaker Grille Molding (2) >> Remove - Radio Front Speaker Grille Molding Replacement




9.
[Click here for full size](#)

10. Release the retainer clips with a suitable trim tool and pull the instrument upper trim panel cover (1) rearward to remove.


Installation Procedure




1.
Click here for full size
2. Instrument Panel Upper Trim Panel Cover (1) >> Install




3.
Click here for full size
4. Radio Front Speaker Grille Molding (2) >> Remove - Radio Front Speaker Grille Molding Replacement



5. [Click here for full size](#)
6. Install the left instrument panel trim pad radio speaker opening cover (1). Instrument Panel Trim Pad Radio Speaker Opening Cover Replacement



7. [Click here for full size](#)
8. Install the left windshield garnish molding (2). Windshield Garnish Molding Replacement



9.
Click here for full size

10. Install the left body hinge pillar garnish molding (1).Body Hinge Pillar Garnish Molding Replacement

mcx30.com