


2022 CHEVROLET CORVETTE SERVICE MANUAL

- SEARCH

- 1. Body Hardware and Trim
- 2. Interior Trim and Paneling
- 3. Repair Instructions
- 4.

Front Side Door Pull Handle Bracket Replacement



[Click here for full size](#)
Front Side Door Trim Replacement

Fastener Caution.>

Tighten

3 N-m (27 lb in)

Callout	Component Name
Preliminary Procedure	
1>	Front Side Door Armrest Bracket Bolt [2>x] Caution : Refer to:
2>	Front Side Door Pull Handle Bracket Procedure Transfer components as necessary.