


2022 CHEVROLET CORVETTE SERVICE MANUAL

- SEARCH

- 1. [Body Hardware and Trim](#)
- 2. [Interior Trim and Paneling](#)
- 3. [Repair Instructions](#)
- 4.

Front Side Door Sill Garnish Molding Replacement



[Click here for full size](#)
[Body Hinge Pillar Garnish Molding Replacement](#)

Callout	Component Name
Preliminary Procedure	
1	Front Side Door Sill Garnish Molding Procedure 1. Starting at the rear of the garnish molding, pull upward at the B-Pillar joint to disengage garnish molding. 2. Work your way forward disengaging all of the garnish molding clips then pull rearward and towards center console to disengage the clips on the forward vertical wall . 3. Reposition the front floor panel carpet as needed.