


2022 CHEVROLET CORVETTE SERVICE MANUAL

- SEARCH

- 1. Engine/Propulsion
- 2. Engine Mechanical - 6.2L (LT2)
- 3. Repair Instructions
- 4.

Valve Rocker Arm Oil Control Valve Harness Replacement



[Click here for full size](#)
Engine Block Valley Cover Replacement

Fastener Caution.

Tighten

10 N-m (89 lb in)

Callout	Component Name
Preliminary Procedure	
1	Valve Lifter Oil Solenoid Valve Connector [4x]
2	Positive Crankcase Ventilation Oil Separator Bolt [4x]
	Caution: Refer to
3	Valve Rocker Arm Oil Control Valve Harness
4	Wiring Harness Connector Seal
	Procedure Install a NEW seal. Do NOT reuse the old seal.