


2022 CHEVROLET CORVETTE SERVICE MANUAL

- SEARCH

- 1. Body Hardware and Trim
- 2. Interior Trim and Paneling
- 3. Repair Instructions
- 4.

Quarter Window Trim Finish Panel Replacement (Coupe)



Click here for full size
Rear Compartment Closeout Upper Panel Replacement

-

Headlining Rear Trim Panel Replacement

- Disconnect the seat belt from the tensioner.

Front Seat Belt Retractor Replacement

Callout	Component Name
Preliminary Procedures	
1.	

Callout	Component Name
1	Quarter Window Trim Finish Panel Note: Use a flat bladed plastic trim tool. Procedure 1. Pull outward to release integral clips. 2. Release the seat belt bezel from the quarter window trim finish panel and feed the seat belt through the opening in the quarter window trim finish panel. 3. { If equipped } Disconnect the electrical connector. 4. Transfer components as necessary.