

2022 CHEVROLET CORVETTE SERVICE MANUAL

- **SEARCH**

1. Engine/Propulsion
2. **Exhaust**
3. Repair Instructions
- 4.

Exhaust Front Bracket Replacement - Left Side


Removal Procedure

Warning:


In order to avoid being burned, do not service the exhaust system while it is still hot. Service the system when it is cool.

Warning:


Avoid contact with HOT components. Wear safety glasses and protective gloves to avoid personal injury.




1. [Click here for full size](#)
2. Rear Wheelhouse Liner - Left Side (4) >> Remove - Rear Wheelhouse Liner Replacement - Left Side



3.
[Click here for full size](#)
4. Exhaust Hanger Bracket Bolt (1) >> Remove




5.
[Click here for full size](#)
6. Exhaust Hanger Bracket Bolt (1) >> Remove




7. [Click here for full size](#)
8. Exhaust Front Bracket (1) >> Remove


Installation Procedure




1. [Click here for full size](#)
2. Exhaust Front Bracket (1) >> Install



3. [Click here for full size](#)
4. Caution:
Refer to Fastener Caution.
5. Exhaust Hanger Bracket Bolt (1) >> Install and tighten 22 N-m (16 lb ft)



6. [Click here for full size](#)
7. Exhaust Hanger Bracket Bolt (1) >> Install and tighten 22 N-m (16 lb ft)



8.
[Click here for full size](#)

9. Rear Wheelhouse Liner - Left Side (4) >> Install - Rear Wheelhouse Liner Replacement - Left Side

mcx30.com