


2022 CHEVROLET CORVETTE SERVICE MANUAL

- SEARCH

- 1. [Engine/Propulsion](#)
- 2. [Exhaust](#)
- 3. [Repair Instructions](#)
- 4.

Exhaust Front Hanger Replacement (Right Side)



[Click here for full size](#)
[Air Cleaner Assembly Replacement](#)

Fastener Caution.

Tighten

22 N-m (16 lb ft)

Fastener Caution.

Tighten

22 N-m (16 lb ft)

Callout	Component Name
Warning:	
In order to avoid being burned, do not service the exhaust system while it is still hot. Service the system when it is cool.	
Warning:	
Avoid contact with HOT components. Wear safety glasses and protective gloves to avoid personal injury.	
Preliminary Procedure	

Callout	Component Name
1	Catalytic Converter Brace Bolt [2x] Caution: Refer to
2	Exhaust Hanger Bracket Bolt Caution: Refer to
3	Exhaust Front Hanger Procedure Transfer components as necessary.

mcx30.com