


2022 CHEVROLET CORVETTE SERVICE MANUAL

- SEARCH

- 1. [Engine/Propulsion](#)
- 2. **Exhaust**
- 3. [Repair Instructions](#)
- 4.

Exhaust Rear Muffler Insulator Replacement



[Click here for full size](#)
Fastener Caution.

Tighten 22 N-m (16 lb ft)

Callout	Component Name
Warning: In order to avoid being burned, do not service the exhaust system while it is still hot. Service the system when it is cool.	
Warning: Avoid contact with HOT components. Wear safety glasses and protective gloves to avoid personal injury.	
1	Exhaust Muffler Hanger Bracket Bolt [2x] Caution: Refer to
2	Exhaust Rear Muffler Insulator Note: The rear bumper fascia is removed for illustration purposes only.