

# 2022 CHEVROLET CORVETTE SERVICE MANUAL

- SEARCH

1. General Information
2. Air/Wind Noise
3. Repair Instructions
- 4.

## Interior Windnoise

Warning:

Refer to Assistant Driving Warning.

Interior windnoise is not heard when the window is lowered. Interior windnoise is caused by the air leaving the inside of the vehicle through a seal or a seam.

1. Tape over the relief valves to cause added air pressure within the vehicle.
2. Test drive the vehicle and listen for windnoise or a whistle.
3. Pull the vehicle over and make the temporary repairs using masking tape. If you cannot determine the source of the windnoise, perform one or more of the following diagnostic tests:
4.
  - Air Pressure Test
  - Soap Suds or Bubble Test
  - Tracing Powder or Chalk Test