


2022 CHEVROLET CORVETTE SERVICE MANUAL

- **SEARCH**

1. General Information
2. Waterleaks
3. Repair Instructions
- 4.

Body Waterleak Repair



[Click here for full size](#)

Warning:

If the vehicle interior is exposed to moisture and becomes soaked up to the level of the sensing and diagnostic module (SDM), the SDM and SDM harness connector must be replaced. The SDM could be activated when powered, which could cause airbag deployment and result in personal injury.

Depending on the location of the waterleak, you may have to remove certain interior components in order to repair the leak.

1. If the floor carpet is wet refer to Floor Carpet Drying.