


2022 CHEVROLET CORVETTE SERVICE MANUAL

- SEARCH

- 1. [Body Hardware and Trim](#)
- 2. [Interior Trim and Paneling](#)
- 3. [Repair Instructions](#)
- 4.

Rear End Trim Cover Panel Replacement



[Click here for full size](#)
Rear Compartment Front Lower Partition Replacement

•

Roof Lift Off Panel/Window Stowage Rear Bracket Replacement

Convenience Net Retainer Replacement

Callout	Component Name
Preliminary Procedures	
1.	
1	Convenience Net Retainer [4x]
	Procedure
	Remove the convenience net retainers on each side of the courtesy lamps.
2	Rear Compartment Side Trim Retainer [2x]
	Note:
	Use a flat bladed plastic trim tool.

Callout	Component Name
3	Rear End Trim Cover Panel Note: Ensure the auxiliary rear compartment latch release handle is inserted through the opening in the rear end trim cover panel prior to being secured. 1. Disconnect the electrical connectors. 2. Lift up and over to avoid displacing the latch spring.

mcx30.com